









d_0	$\varnothing 10\text{mm}$







A8 $h_{\text{nom}} = 85\text{mm} \mid t_{\text{fix}2} = 0 \dots 10\text{mm}$

HUS3-C 10	$t_{\text{fix}1}$	$t_{\text{fix}1} + t_{\text{fix}2}$
10x90	5 mm	5...15 mm
10x100	15 mm	15...25 mm






d_0	$\varnothing 10\text{mm}$	$\varnothing 10\text{mm}$	$\varnothing 8\text{mm}$



B5

	$h_{\text{nom}1}$	$h_{\text{nom}2}$	$h_{\text{nom}3}$
HUS3-C 10	=55mm	=75mm	=85mm
10x70	15 mm	-	-
10x90	35 mm	15 mm	-
10x100	45 mm	25 mm	15 mm



		d_0
d_0	$\varnothing 10\text{mm}$	

