











	HSA	HSABW	HSA-R	HSA-R2
M10 5/-/-	✓	✓	✓	-
M10 20/10/-	✓	✓	✓	✓
M10 35/25/-	✓	-	✓	-
M10 50/40/10	✓	-	✓	-
M10 70/60/30	✓	-	✓	-
M10 90/80/50	✓	-	✓	-
M10 105/95/65	✓	-	-	-



HSA	t _{ex1} [mm]	t _{ex2} [mm]	t _{ex3} [mm]
M10 5/-/-	5	-	-
M10 20/10/-	20	10	-
M10 35/25/-	35	25	-
M10 50/40/10	50	40	10
M10 70/60/30	70	60	30
M10 90/80/50	90	80	50
M10 105/95/65	105	95	65

HSA	1	2	3
h _{nom} [mm]	50	60	90
h _{min} [mm]	100	120	160
S _{min} [mm]	50	50	50
C _{min} [mm]	50	40	40



SIW 6AT-A22 + SI-AT-A22
 SIW 4AT-22 + SI-AT-22
 SIW 6AT-22 + SI-AT-22