



HSV	M8		M10		M12		M16	
	$h_{nom1}$	$h_{nom2}$	$h_{nom1}$	$h_{nom2}$	$h_{nom1}$	$h_{nom2}$	$h_{nom1}$	$h_{nom2}$
$h_{nom}$ [mm]	39	49	51	61	62	77	81	96
$h_{min}$ [mm]	100	100	100	120	140	140	130	170
$S_{min}$ [mm]	60	60	70	70	80	80	120	100
$C_{min}$ [mm]	60	60	70	70	90	90	120	100
$d_f$ [mm], min	9		12		14		18	
$h_1$ [mm], min	45	55	60	70	70	85	90	105
$d_o$ [mm]	8		10		12		16	
SW [mm]	13		17		19		24	
$T_{inst}$ [Nm]	15		30		50		100	

	$t_{fix}$ , max [mm]	
	$h_{nom1}$	$h_{nom2}$
M8 x 75	20	10
M10 x 90	25	15
M10 x 100	35	25
M12 x 100	20	5
M12 x 110	30	15
M12 x 120	40	25
M12 x 150	70	55
M16 x 120	15	-
M16 x 140	35	20

	$t_{fix}$ , max [mm]	
	$h_{nom1}$	$h_{nom2}$
M8 x 75	20	10
M10 x 90	20	10
M12 x 100	15	-
M12 x 110	25	10
M12 x 120	35	20
M12 x 150	65	50
M16 x 120	10	-
M16 x 140	30	15

