









d_0	$\varnothing 8\text{ mm}$







A8 $h_{\text{nom}} = 70\text{ mm} \mid t_{\text{fix}2} = 0 \dots 10\text{ mm}$

HUS3-C 8	$t_{\text{fix}1}$	$t_{\text{fix}1} + t_{\text{fix}2}$
8x75	5 mm	5...15 mm
8x85	15 mm	15...25 mm






d_0	$\varnothing 8\text{ mm}$	$\varnothing 8\text{ mm}$	$\varnothing 6\text{ mm}$



B5

	$h_{\text{nom}1}$	$h_{\text{nom}2}$	$h_{\text{nom}3}$
HUS3-C 8	=50mm	=60mm	=70mm
	$t_{\text{fix}1}$	$t_{\text{fix}2}$	$t_{\text{fix}3}$
8x65	15 mm	-	-
8x75	25 mm	15 mm	-
8x85	35 mm	25 mm	15 mm



		d_0
d_0	$\varnothing 8\text{ mm}$	

