









d_0	$\varnothing 10\text{mm}$







A8 $h_{\text{nom}} = 85\text{mm} \mid t_{\text{fix}2} = 0 \dots 10\text{mm}$

HUS3-H 10	$t_{\text{fix}1}$	$t_{\text{fix}1} + t_{\text{fix}2}$
10x90	5 mm	5...15 mm
10x100	15 mm	15...25 mm
10x110	25 mm	25...35 mm
10x130	45 mm	45...55 mm
10x150	65 mm	65...75 mm






d_0	$\varnothing 10\text{mm}$	$\varnothing 10\text{mm}$	$\varnothing 8\text{mm}$























B5

	$h_{\text{nom}1}$	$h_{\text{nom}2}$	$h_{\text{nom}3}$
HUS3-H 10	=55mm	=75mm	=85mm
	$t_{\text{fix}1}$	$t_{\text{fix}2}$	$t_{\text{fix}3}$
10x60	5 mm	-	-
10x70	15 mm	-	-
10x80	25 mm	5 mm	-
10x90	35 mm	15 mm	5 mm
10x100	45 mm	25 mm	15 mm
10x110	55 mm	35 mm	25 mm
10x130	75 mm	55 mm	45 mm
10x150	95 mm	75 mm	65 mm



		d_0
d_0	$\varnothing 10\text{mm}$	$\varnothing 10\text{mm}$





B5

HUS3-H 10	h_{nom1} =55mm	h_{nom2} =75mm	h_{nom3} =85mm
	t_{fix1}	t_{fix2}	t_{fix3}
10x60	5 mm	-	-
10x70	15 mm	-	-
10x80	25 mm	5 mm	-
10x90	35 mm	15 mm	5 mm
10x100	45 mm	25 mm	15 mm
10x110	55 mm	35 mm	25 mm
10x130	75 mm	55 mm	45 mm
10x150	95 mm	75 mm	65 mm