









d_0	$\varnothing 10\text{mm}$







A8

HUS3-HF 10	$h_{nom} = 85\text{mm}$	$t_{fix2} = 0 \dots 10\text{mm}$
10x100	15 mm	15...25 mm
10x110	25 mm	25...35 mm






d_0	$\varnothing 10\text{mm}$	$\varnothing 10\text{mm}$	$\varnothing 8\text{mm}$



B5

	h_{nom1}	h_{nom2}	h_{nom3}
HUS3-HF 10	=55mm	=75mm	=85mm
10x60	5 mm	-	-
10x80	25 mm	5 mm	-
10x100	45 mm	25 mm	15 mm
10x110	55 mm	35 mm	25 mm



	d_0
$\varnothing 10\text{mm}$	

