





















HUS3-P	 h_1	 h_1	t_{fix}
6 x 40	50 mm - t_{fix}	43 mm - t_{fix}	0 ... 5 mm
6 x 60	70 mm - t_{fix}	63 mm - t_{fix}	5 ... 25 mm
6 x 80	90 mm - t_{fix}	83 mm - t_{fix}	25 ... 45 mm





1.1			
			
d_0	Ø 6 mm	Ø 6 mm	Ø 5 mm









3.1			
h_{nom}	35 mm	55 mm	55 mm
	✓	✓	✗
	✓	✓	✗
	✗	✗	✗
	18 Nm	25 Nm	12 Nm








HUS3-P	 h_1	t_{fix}
6 x 40	43 mm - t_{fix}	0 ... 5 mm
6 x 60	63 mm - t_{fix}	5 ... 25 mm
6 x 80	83 mm - t_{fix}	25 ... 45 mm



6.1

	SIW14-A	✓
	SIW 22-A	✓
		18 Nm

